

I. Warranty Book

Warranty card No. (warranty book code number):

Date of autogas system installation:

22/11/2017

(first connection to a PC with AC GAS SYNCHRO / AC STAG software).

Vehicle information:

manufacturer, model and year
of production:

VOLVO S40

Capacity and horsepower:

Registration plate No.:

UHO 7985

VIN number:

Mileage:

49.150

km/miles (delete as needed).

II. Technical parameters of the installed autogas system

1. Reducer:

STAG AC ISO

serial number/s:

2. Tank:

serial number:

3. STAG control system:

STAG GBOX plus

serial number:

(controller number in AC GAS
SYNCHRO / AC STAG software)

4. Injection rail:

STAG AC NO2-4

serial number/s:

I hereby accept the warranty conditions presented herein

ΑΦΟΙ Κ. ΓΑΛΕΑΔΗ Ο.Ε.

ΑΝΤΙΠΡΟΣΩΠΕΙΕΣ - ΕΙΣΑΓΩΓΕΣ - ΕΜΠΟΡΙΑ

ΗΛΕΚΤΡΟΝΙΚΩΝ ΣΥΣΤΗΜΑΤΩΝ ΗΧΟΥ & ΕΙΚΟΝΑΣ

ΑΞΕΣΟΥΑΡ - ΠΡΟΜΗΘΕΙΕΣ - ΚΙΝΗΤΗ ΤΗΛΕΦΩΝΙΑ

ΤΟΠΟΘΕΤΗΣΕΙΣ ΣΥΣΤΗΜΑΤΩΝ

ΕΛΕΥΘΕΡΙΑΣ 46 - Τ.Κ. 56430 ΣΤΑΥΡΟΥΠΟΛΗ

ΤΗΛ. 2310 681313 FAX 2310 688383

ΑΦΜ 084272730 ΔΟΥ ΕΛΛΕΝΙΚΗΣ

STAG
autogas systems

22/11/17
date

.....
signature of the vehicle owner

VII. Periodic inspections

Periodic inspection after 1000 km /no charge/		
Date		
Mileage		
Next inspection		
Service operations	Yes/No	Remarks
Check fixing of the gas tank and other system components		
Check gas injectors, fixing elements and supply lines		
System leak test		
Check STAG controller parameters, petrol correcting factors and injector pulsing time		
Service point stamp and signature of the inspector		

STAG[®]
autogas systems

Inspection	10 000 km	
Date	22/08/18	
Mileage	64.320	
Next inspection		
Service operations	Yes/No	Remarks
Check gas injectors, fixing elements and supply lines	✓	αλλαγή υγραερίων
System leak test	✓	καθαρισμός inverter
Check STAG controller parameters, petrol correcting factors and injector pulsing time	✓	ελέγχος H11
Replacement of the liquid gas filter	✓	
Replacement of the vapor gas filter	✓	
Service point stamp and signature of the inspector		

ΓΑΛΕΑΔΗ & ΣΙΑ Ο.Ε.
ΤΟΠΟΘΕΤΗΣΗ ΣΥΣΤΗΜΑΤΩΝ
ΥΓΡΑΕΡΙΟΚΙΝΗΣΗΣ
Κ. ΠΑΛΑΙΟΛΟΓΟΥ 65 ΘΕΣ/ΝΙΚΗ ΤΚ. 564 30
ΤΗΛ. 2310 68 83 83 - FAX. 2310 68 13 13
ΑΦΜ. 999 293 818 ΔΟΥ. Ε' ΘΕΣ/ΝΙΚΗΣ

VII. Periodic inspections

Inspection	20 000 km		30 000 km		40 000 km	
Date	11/07/19		12/01/20		12/06/21	
Mileage	80.491		97.802		107.230	
Next inspection						
Service operations	Yes/No	Remarks	Yes/No	Remarks	Yes/No	Remarks
Check gas injectors, fixing elements and supply lines	✓	αλλαγή βαλβερών + universal	✓	αλλαγή υγραερίων		αλλαγή MAP PS-02
System leak test	✓	υγραέρια	✓	βαλβερών (universal)		+ αναρρόφησης
Check STAG controller parameters, petrol correcting factors and injector pulsing time	✓	ελέγχος Η/Υ	✓	ελέγχος Η/Υ		ελέγχος Η/Υ
Replacement of the liquid gas filter	✓		✓			
Replacement of the vapor gas filter	✓		✓			

Service point stamp and signature of the inspector

ΓΑΛΕΑΔΗ & ΣΙΑ Ο.Ε.
ΤΟΠΟΘΕΤΗΣΗ ΣΥΣΤΗΜΑΤΩΝ ΥΓΡΑΕΡΙΟΚΙΝΗΣΗΣ
 Κ. ΠΑΛΑΙΟΛΟΓΟΥ 65 ΘΕΣ/ΝΙΚΗ ΤΚ. 564 30
 ΤΗΛ. 2310 68 83 83 - FAX. 2310 68 13 13
 ΑΦΜ. 999 293 818 ΔΟΥ. Ε' ΘΕΣ/ΝΙΚΗΣ

STAG[®]
 autogas systems

ΓΑΛΕΑΔΗ & ΣΙΑ Ο.Ε.
ΤΟΠΟΘΕΤΗΣΗ ΣΥΣΤΗΜΑΤΩΝ ΥΓΡΑΕΡΙΟΚΙΝΗΣΗΣ
 Κ. ΠΑΛΑΙΟΛΟΓΟΥ 65 ΘΕΣ/ΝΙΚΗ ΤΚ. 564 30
 ΤΗΛ. 2310 68 83 83 - FAX. 2310 68 13 13
 ΑΦΜ. 999 293 818 ΔΟΥ. Ε' ΘΕΣ/ΝΙΚΗΣ

VII. Periodic inspections

Inspection	50 000 km		60 000 km		70 000 km	
Date	28/08/21					
Mileage	111.351					
Next inspection	121.351					
Service operations	Yes/No	Remarks	Yes/No	Remarks	Yes/No	Remarks
Check gas injectors, fixing elements and supply lines	✓	αλλαγή φίλτρων				
System leak test	✓	valve +				
Check STAG controller parameters, petrol correcting factors and injector pulsing time	✓	universal ελεγχος				
Replacement of the liquid gas filter	✓	HIY				
Replacement of the vapor gas filter	✓					

Service point stamp
and signature
of the inspector

ΓΑΛΕΑΔΗ & ΣΙΑ Ο.Ε.
ΤΟΠΟΘΕΤΗΣΗ ΣΥΣΤΗΜΑΤΩΝ
ΥΓΡΑΕΡΙΟΚΙΝΗΣΗΣ

Κ. ΠΑΛΑΙΟΛΟΓΟΥ 65 ΘΕΣ/ΝΙΚΗ ΤΚ. 564 30

ΤΗΛ. 2310 68 83 83 - FAX. 2310 68 13 13

999 293 818 ΔΟΥ. Ε' ΘΕΣ/ΝΙΚΗΣ

STAG
autogas systems